

For Piezo Tips

- 1. Place the tip on the hand piece and tighten with your fingers
- 2. Slide the wrench over the tip (the tip should be in the center of the wrench)
- 3. Turn the wrench clockwise 3 full turns to lock the tip in place